


# 578VU Pro can not see the BT module (In menu)

Take the head off.  
Remove the Ribbon at both ends.  
Refit ribbon and make sure fitted correctly.

The menu will now see the BT module.



[You will need a Torx/Hex Screwdriver](#)

<http://tiny.cc/AnytoneDMR>