Analog APRS will not work

This is most likely down to a bad/corrupted Codeplug.

You need to do this with your codeplug

- 1. Export all CSV (a.)
- 2. In the CPS click on File NEW
- 3. Import all CSV (a.)
- 4. Skip going over Optional Settings for now (b.)
- 5. Save this codeplug so you can find it again
- 6. MCU reset the radio and set date and time
- 7. Send this new codeplug to the radio
- 8. Test your APRS now and it should work
- a. How to Export and Import All CSV
- b. Optional Settings <u>Settings I Use</u>

Also read this <u>Analog APRS Anytone 878/878plus/578</u>

http://tiny.cc/AnytoneDMR